

## 2023 Highway Maintenance Conference

# Bridge Maintenance North Region




Brandon Boatman, P.E.


North & Superior Region Region Bridge Engineer boatmanb@michigan.gov Chad Skrocki, P.E.

North Region Asst. Region Bridge Engineer skrockic@michigan.gov





### Scaling



×



### Scaling





### **Deck Patching**





## **Deck Patching**







#### Healer/Sealer





## **Epoxy Overlay**











































#### Shallow Patching - Fast Set TRANSPO T-17





#### Shallow Patching - Fast Set TRANSPO T-17



## **Expansion Joint Replacement**


















































A DESCRIPTION OF THE PARTY OF T









































Latex Additive



**Concrete Bonding Adhesive** & Acrylic Fortifier

Sila Corperation, 201 Polito Are, Jondhurst, NJ 00701 Tel: 201-933-8000 www.Silausa.com Importado por: Sila Maxicana S.A. de C.V. Carr Ubre a Celaya. Km 85, Frace. Industria Bahavana. Tel: (42) 2 38 58 00 R.F.C. SME 78130 827 Nacde in USA by Silea Corp. Hecho en E.U.A. HMIS H-1, F-1, R-0, PPE-B In Cases of Emergency Call Chemitree: 1 -800-424.9300





















Michigan Department of Transportation













Michigan Department of Transportation



## **Questions?**

